so will cause deadness and sourness in Ale or Beer in a short time, for the goodness of the Malt contributes much to the prefervation of all Ales and Beeff. Then the water must be drain'd from it very well, and it will come equal and better on the floor, which may be done in twelve or sixteen Hours in temperate weather, but in cold near thirty. From the Cistern it is put into a square Hutch or Couch, where it must lye thirty Hours for the Officer to take his Gage, who allows four Bushels in the Score for the Swell in this or the Ciftern, then it must be work'd Night and Day in one or two Heaps as the weather is cold or hot, and turn'd every four, fix or eight Hours, the outward part inwards and the bottom upwards, always keeping a clear floor that the Corn that lies next to it be not chill'd; and affoon as it begins to come or spire, then turn it every three, four or five Hours, as was done before according to the temper of the Air, which greatly governs this management, and as it comes or works more, so must the Heap be spreaded and thinned larger to cool it. Thus it may lye and be work'd on the floor in feveral Parallels, two or three Foot thick, ten or more Foot broad, and fourteen or more in length to Chip and Spire, but not too much nor too fast; and when it